



NOTE:
STABILIZE BEAMS AND SLABS
UNTIL ALL GROUTING AND
WELDING IS COMPLETE.

TYPICAL SECTION: 8" PRECAST SLAB
END BEARING ON WF SPANDREL BEAM